

# Runway Condition Code (RWYCC) EDQM



20.09.2026 14:08:03

Friction Section C

Friction Section B

Friction Section A



**EDQM20.09.2026 14:08:03/26/6/6/6/100/100/100/00/00/00/DRY/DRY/DRY/30**

Zeitangabe: Locale Zeit

Time Indication: local time

Der Runway Condition Code (RWYCC) wurde mit der Runway Condition Assessment Matrix (RCAM) erstellt.

The Runway Condition Code (RWYCC) was created using the Runway Condition Assessment Matrix (RCAM).

Flughafen Hof Plauen GmbH & Co.KG

Pirk 20

95032 Hof

Erfasser: Fickenscher Thomas